

VEHICLE INSPECTION REPORT

FX13CTE

SHIBAURA CM374

Inspection

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Doncaster	Fuel Type	Diesel	Gearbox	Hydrostatic
Reg. date	01/03/2013	Colour	RED	Axle Combi	4x4
Year	2013	VIN	10353		
Mileage	2,307 Hours TBC	Body Style	Ride on Mower		

MUTHING MUFM160 MOWER DECK (YEAR 2013) S/N 3117305

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



